Heritage At Risk Register

Granary at Preston Farm BINDERTON

Asset Type:
Grid Reference:
Parish:
Conservation Area:
SDNP:
Description:

Priority: Reason for Risk: Registered: Last Assessed: Ownership: Current Status:

Curtilage Listed Building – Grade II 485428, 111183 West Dean No Yes Timber-framed staddle-stone granary to south-east of farmhouse, north of farmvard. Corrugated asbestos roof. Wide vertical timber boarding, overclad with modern horizontal timber. А Deterioration. Neglect. Lack of use. November 2013 26 November 2013 Trust East elevation timber sill plate severely deteriorated, south east corner rotten, bearing on staddle stone slipping. Modern brick piers to north-east corner. Wide vertical timber cladding to west and south elevations, partially overclad with horizontal timber. North and east elevations corrugated metal sheeting internally in place of cladding. Timber sill-plate and floor beam deteriorated bearing on staddle stone below door.

Photograph 2013



Priority

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- **C** Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.