Heritage At Risk Register

Chapel at Horsham Road Cemetery PETWORTH

Asset Type: Grid Reference: Parish: Conservation Area: SDNP: Description:

Priority: Reason for Risk: Registered: Last Assessed: Ownership: Current Status: Unlisted Building 497821, 122354 Petworth Petworth Yes Victorian chapel in the grounds of Horsham Road Cemetery. C General deterioration. 1999 19 April 2012

Main roof structure appears to be under stress with failure resulting in places. Tiling pattern remains legible. Victorian carved barge-boards in-tact and repairable. Tower and porch suffer from loss of tiles and structural failure. Tower partially lost due to failed roof structure. Severe fractures to NE and NW corner of north protrusion suggesting the volume is pulling away from the core. Iron rain goods lost. Majority of the leaded windows are missing. Internally, structural beam supported by metal prop. Lath and plaster ceilings failing in parts.



Photograph 2012

Priority

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- **C** Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.