Heritage At Risk Register

Binderton Chapel

Asset Type: Grid Reference: Parish: Conservation Area: SDNP: Description:

Priority: Reason for Risk: Registered: Last Assessed: Ownership: Current Status: Listed Building – Grade II 485046 110664 West Dean No Yes 17C former chapel constructed of 2" brick and squared flint laid to course. С Some deterioration. Vulnerable. July 2012 July 2012 Trust Section of door pilaster coming loose. Some brick spalling, but generally in good condition. Not watertight, but covered with flat felt roof. Extensive plant growth.



Photograph 2012

Priority

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- **C** Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- **F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.