Heritage At Risk Register

Remains of Treyford Church (St Mary's Church) TREYFORD

Asset Type:

Grid Reference: Parish: Conservation Area: SDNP: Description:

Priority: Reason for Risk: Registered: Last Assessed: Ownership: Current Status: Listed Building – Grade II*, Scheduled Ancient Monument 482429, 118685 Elsted and Treyford No Yes Remains of the east, south and west walls of the 13C church consisting of chancel and nave. 3 lancet windows in east wall. Е Overgrown and in need of stabilizing. 1991 14 February 2012 Private Mortar repairs made. Lime mortar consolidation recently undertaken (hessian still extant).



Photograph 2012

Priority

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- **C** Slow decay; no solution agreed.
- **D** Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.